## U.S. Environmental Protection Agency Region 7 726 Minnesota Avenue, Kansas City, KS 66101

## NOTICE OF INSPECTION

Resource Conservation and Recovery Act (RCRA) Public Law 94-580, as amended.

Subtitle I Underground Storage Tanks Hour In: 12:35 Date Facility Name Inspector Casin Omaha Fuel Plaza Out: 2:20 EPA/State ID# Street Address Facility Representative(s)

Hirlan Richard City Onawa State Zip Code 51040 TA Reason for Inspection: LD Entry by Consent K Warrant () To determine the extent of compliance with the above referenced law, which may require the collection of samples, documents and/or photographs. Other (Specify) Documents and/or Photos collected (describe below) The facts established by this inspection will be reviewed by personnel in the EPA Regional Office. A final determination of your facility's compliance with the EPA regulations will be made as a result of this review. The review may reveal additional violations. Signature of Receipt of this Notice of Inspection acknowledged

## US EPA - Region VII UST FACILITY INSPECTION CHECKLIST

Owner Name Omaha Tribe  Street Address  City  County  State  Zip Code  Contact  Phone		Facility Name Casin Once ha ID# WA  Street Address  City County State Zip Code  Contact at Location Phone							
					III. Tank/Piping Information	Tank 1	Tank 2	Tank 3	Tank 4
					Type of Tank (has tank been lined?)				
					Year Installed	all 1996			
					Capacity of Tank (in gallons)	see comments			
					Substance Stored	11	•	•	
Indicate tanks manifolded	? /ook	5 like some	maybe, can	'Htell					
Piping Material	TC Own; +	017	, ,	W. 120					
IV.A. Release Detection For Tanks	Methods: TTT &	IC, ATG, VM, GWM, SIF	R, Int. Mon., MTG						
Indicate Method	AYC E	FCO 2000							
IV.B. Release Detection For Piping	Methods: LTT, 1	/M, GWM, SIR, Sec. Cor	., Continual Line Moni	toring					
Pressurized (P), Suction (S), Safe (SS)	Pres all								
Line Leak Dectector (yes/no) and:									
Indicate Method	db/ well pipe	Sump senso	15						
V. Corrosion and Spill/Overfill Protecti	ALL SALES OF THE SECOND	osion Protection: FRP, G							
Type of Corrosion Protection: Tanks	/9	actually Total	Containment	acketed					
Piping	Ouni-flex								
Overfill Protection (Yes/No; Method)	ATG & ball	float valve	5						
Spill Protection (Yes/No)	Yes - all			5010, 2010					
VI. Financial Responsibility			AND SOME THE RES						
Does O/O have evidence of financial assurance	mechanism used? (circ	le one) YES NO M	echanism:						
VII. Comments/Site Information	THEORIGINATION COSCIONAL								
Tacility rep does in think 2, 18000 & 1	, 10000 are d	iesel, rest a	asoline	k					
VIII. Inspector's Signature:	学是一种产业(B	· 计图像数据表	Da	nte:					